

Differences between modelling and experimental results may be due to:

(Simple to correct)

- **Small forgotten metal objects such as screws**
- **Meshing errors (unchecked by user, but may perhaps also require finer meshing)**
- **Imperfect absorbing planes (software issue)**

(Model input errors; more difficult)

- **Imperfect sheet metal joints (point welds, foldings)**
- **Errors in dielectric data of supports and LOADS; (temperature dependence, drying?)**

(Imperfect experimental conditions)

- **Sensitive mode imbalances in combination with magnetron frequency pulling**